



## **DIR-842 Firmware Release Notes**

**Firmware: FW v1.05B02**

**Hardware: Rev. Ax**

**Date: June 4, 2019**

### **Problem Resolves:**

- Heap-based buffer overflow in dnsmasq before 2.78 allows remote attackers to cause a denial of service (crash) or execute arbitrary code via a crafted DNS response.

(CVE-2017-14491)

---