



## **DIR-868L Software Release Notes**

**Firmware: v1.06**

**Hardware: A1**

**Date: 2013/11/22**

### **Problems Resolved:**

1. Revise PT wrong words
2. Close Channel 52 for TW domain
3. Fix LED behavior on client mode

### **Enhancements:**

None

### **Note:**