



D-Link Firmware Release Notes

Model Name: DIR-L1900

HW Version: A1

FW Version: v1.03B03

Notes:

1. Revise Security Mode : WPA2PSK-AES
2. ALG default settings are enabled.

Problems Resolved:

- 1 Parental control issue-
 - 1.1 DUT Network is not working after setup parental control to one wireless client
 - 1.2 Enable Parental control causes the client is always in blocked list
 - 1.3 Client gets speed limitation after changing wireless connection.
- 2 Enable and disable parental control on uplink router few times causes blocked wifi STA still can access Internet
 - 2.1
- 3 IOT issue:
 - 3.1 Increase setmultipleaction REBOOT to 165 seconds for WiFi APP on iphone 5s connection IOT issue.
- 4 FW ver1.02 Bug fix
 - 4.1 DUT configuration (SSID) missing or crashed after FOTA upgrading.
 - 4.2 Remove MVE in mDNS and HNAP. (for WiFi APP with unsupport Mesh model).
 - 4.3 Fix DUT restore factory default after Automatic Firmware Upgrade
(Update DUT automatically)