

# **DIR-X1560 A1 Firmware Release Notes**

**Firmware: 1.03B02** 

Hardware: A1 Date: 2020/08/13

Note:

N/A

## **Problems Resolved:**

- 1. Schedule rule is unable to be saved when setting too many blocks.
- 2. Device may reboot in some corner use cases.
- 3. TKIP error result in wireless connection failure.
- 4. Quick VPN fails on some Android phones or tablets.
- 5. Client list information error with extenders connected to DUT

#### **Enhancements:**

- 1. Improved wireless stability.
- 2. Improved FW query time.
- 3. Improved Internet type detection flow.
- 4. Improved security.

#### **Known Issues:**

1. Device may reboot in BT stress test occasionally.

**Firmware: 1.02B01** 

Hardware: A1 Date: 2020/5/12

Note:

N/A

#### **Problems Resolved:**

- 1. Fixed 802.11kv bug.
- 2. Modified session length of lighttpd from 10 to 32.

#### **Enhancements:**

**D-Link Corporation confidential** 



N/A

**Firmware: 1.01B03** 

Hardware: A1 Date: 2020/5/12

Note:

N/A

## **Problems Resolved:**

- 1. PPTP/L2TP failure sometimes using domain name as server address.
- 2. Fix bug that the MAC address of br0 becomes the same with WLAN interface occasionally.
- 3. Keep admin password unchanged after restoring external config file.

#### **Enhancements:**

- 1. Add support to WPA2-PSK only.
- 2. Enable AirTime Fairness by default.
- 3. Update Web GUI version.

### **Known Issues:**

N/A