



**Firmware Version:** V2.02  
**Prom Code Version:** N/A  
**Published Date:** 2015/09/16

**Content:**

Upgrading Instructions:..... 2  
New Features: ..... 2  
Problems Fixed:..... 3  
Known Issues:..... 5  
Related Documentation:..... 5

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/12/04	DNR-202L	A1
V1.01	2014/06/20	DNR-202L	A1
V1.02	2014/09/18	DNR-202L	A1
V2.00	2015/03/16	DNR-202L	A1
V2.01	2015/08/14	DNR-202L	A1
V2.02	2015/09/16	DNR-202L	A1

## Upgrading Instructions:

1. Upgrading by using Web-UI

## New Features:

Fireware Version	New Features
V1.00.22	1. New model MP FW release
V1.01.00	1. Update the mydlink agent to 2.0.17-b45
V1.02.01	<ol style="list-style-type: none"> <li>1. Update the mydlink agent to V2.0.18-b08</li> <li>2. Add Universal Model</li> </ol>
V2.00.11	<ol style="list-style-type: none"> <li>1. Change the Web UI follow the DNR-312L style.</li> <li>2. Update the mydlink agent to V2.0.18-b44</li> </ol>
V2.01.01	1. Update the mydlink agent to V2.0.19-b42
V2.02.00	1. Update the mydlink agent to V2.0.19-b80

## Enhancements:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	<ol style="list-style-type: none"> <li>1. Landing page add setting page and even functions by US HQ.</li> <li>2. Modify the live icon description.</li> </ol>
V1.02.01	1. Add Camera support: DCS-930LB1/ DCS-932LB1/ DCS-942LB1/ DCS-6004L/ DCS-6005L/

V2.00.11	1. Disable SSL2.0/3.0/RC4/DES
V2.01.01	1. Support Cameras: DCS-935L / DCS-1201 / DCS-4201 / DCS-4602EV / DCS-4701E / DCS-5029L / DCS-6212L. 2. Support Language : русский.
V2.01.03	1. Support Camera: DCS-960L / DCS-2630L 2. Add Warning message on Chrome & Edge browser

## Problems Fixed:

Firmware Version	Problems Fixed
V1.00.22	N/A
V1.01.00	<ol style="list-style-type: none"> <li>Fixed DLAB Bug DBG13100305: When keying right account and wrong password to register, it would not show any warning message and pass to the next flow.</li> <li>Fixed DLAB Bug DBG13080170: Audio is strange on DCS-931L, DCS-933L and DCS-5020L.</li> <li>Fixed DLAB Bug DBG13090288: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while.(Test with IE8, IE9, Firefox and Chrome)</li> <li>Fixed DLAB Bug DBG13080155: Almost functions could not be worked when first time log in DUT with browser IE7.</li> <li>Fixed DLAB Bug DBG13080041: Playback could not play recording files by speeding up to 1/4/8/16/32 normally. It would stop after a while.(Test with IE8 &amp; IE9)</li> <li>Fixed DLAB Bug DBG13020011: Live view would be in black after enable full screen and glance for a long term.</li> <li>Fixed D-Track HQ20140107000013: Export avi the video and audio will not sync.</li> <li>Fixed D-Track HQ20140113000014: I saw from log that record on 11 Jan. has been deleted due to disk full. However, when I access playback and selected 11 Jan. it still shows red line with records. I selected it to playback, it will show blank on screen.</li> <li>Fixed D-Track HQ20140116000020: The image enhancement button always gray out</li> <li>Fixed D-Track HQ20140128000008: DNR-202L not work playback function over IE11 and Firefox v26.0</li> </ol>
V1.02.01	<ol style="list-style-type: none"> <li>Fixed DLAB Bug DBG13020096: Convert 2 hours recording would cause the browser crashed.</li> <li>Fixed DLAB Bug DBG13090341: Recording of all channels would stop for a while by itself but there is no log about that.</li> <li>Fixed DLAB Bug DBG14050136: Not translate "OSD setting" on live video and playback page in all supported languages.</li> <li>Fixed DLAB Bug DBG14050187: Both Safari and firefox cannot display normally in live video of mydlink.</li> <li>Fixed DLAB Bug DBG13090343: Some sentences are all bold of description in panish language.</li> <li>Fixed DLAB Bug DBG13090314: Export files are not complete. Export 1 hour video but just 6 exported files.(Watermark/ Standard/ AVI file)(Test with DCS-932 and DCS-6818B1)</li> <li>Fixed DLAB Bug DBG14050133: Live video could not be watched on Opera browser normally.(Opera 21.0.1432.67)</li> </ol>

	<ol style="list-style-type: none"> <li>8. Fixed DLAB Bug DBG13090356: Change fixed quality of DCS-3715 to "very high" but it shows "customize" on DCS-3715 UI.</li> <li>9. Fixed DLAB Bug DBG14050134: Live video could not be watched on Safari browser in Mac OS.</li> <li>10. Fixed DLAB Bug DBG13020075: No warning message would popup when convert a recording file without setting the cue-in and cue-out</li> <li>11. Fixed DLAB Bug DBG13020016: FW version on the title of page wouldn't be properly.</li> <li>12. Fixed DLAB Bug DBG13020018: Time bar in PLAYBACK couldn't be visible when browse by non-IE browsers</li> <li>13. Fixed DLAB Bug DBG13020019: Some typos are in the SUPPORT pag</li> <li>14. Fixed the mydlink Bug 8232: There is no live video and playback video on Mac 10.9/ safari 7</li> <li>15. Fixed the mydlink Bug10943: Couldn't watch live view on DNR-202L after update JAVA 7 to 67</li> </ol>
V2.00.09	<ol style="list-style-type: none"> <li>1. Fixed DLAB Bug DBG14120563: Could not always update camera IP and model successfully.</li> <li>2. Fixed the model list can't select at camera search page.</li> <li>3. Fixed the select language the UI will not sync when run the wizard.</li> <li>4. Fixed DLAB Bug DBG15020207: New user account still can login DUT web Playback page.</li> <li>5. Fixed DLAB Bug DBG15020213: DUT didn't support the settings: record on motion, system shutdown but would show in the help page.</li> <li>6. Fixed DLAB Bug DBG14090470: After DUT changed DCS-930LB1/932LB1 frame rate to auto, frame rate setting would be grayed.</li> <li>7. Fixed DLAB Bug DBG15020236: I.E. has stopped working during endurance test.</li> <li>8. Fixed DLAB Bug DBG15020214: DUT couldn't modify user account privileges.</li> <li>9. Fixed DLAB Bug DBG15020215: DUT auto scan interval still is 5 seconds after change to 3 seconds.</li> <li>10. Fixed DLAB Bug DBG15020217: Whether playback a DI recording or motion recording, at initial the recording would show both motion and DI trigger icon then only show motion trigger icon.</li> <li>11. Fixed DLAB Bug DBG15020202: DUT didn't automatic overwrite after HDD full.</li> <li>12. Fixed DLAB Bug DBG15020211: DUT would always show your time setting is not correct after edit schedule.</li> <li>13. Fixed send the incorrect URL to DNR-202L will crash.</li> <li>14. Fixed DLAB Bug DBG15020251: DUT default IP would be 0.0.0.0.</li> </ol>
V2.00.10	<ol style="list-style-type: none"> <li>1. Fixed DLAB Bug DBG15020253: Wizard couldn't search any camera is the same LAN subnet as DUT to add but SetupWizard SE could.</li> </ol>
V2.00.11	<ol style="list-style-type: none"> <li>1. Fixed DLAB Bug DBG15020203: DUT would turn off HDD LED after HDD full but DUT still mounted the HDD.</li> <li>2. Fixed DLAB Bug DBG15030170: Keep triggering camera DI but DUT only event record and send alert mail first 7 minutes.</li> <li>3. Fixed DLAB Bug DBG15030173: DUT playback camera motion recording but the recording couldn't be shown then web UI had no response.</li> <li>4. Fixed DLAB DBG15020217: Whether playback a DI recording or motion recording, at initial the recording would show both motion and DI trigger icon then only show motion trigger icon.</li> <li>5. Fixed DLAB DBG15030164: DUT couldn't set DCS-6112B1 motion area.</li> </ol>
V2.01.04	<ol style="list-style-type: none"> <li>1. Fixed login failed on Windows 10 edge Browser issue.</li> </ol>
V2.02.00	<ol style="list-style-type: none"> <li>1. Fixed DNR-202L Record can't over rewrite.</li> <li>2. Fixed DLAB DBG15070060: The Approtech camera saturation setting</li> </ol>

	<p>maximum is 255 but DUT web UI is 254</p> <p>3. Fixed DLAB DBG15070072: Enable auto daylight saving with timezone Alaska but DUT time is incorrect.</p> <p>4. Fixed DLAB DBG15070074: Enable daylight saving time has been manually offset but DUT time is incorrect.</p>
--	---

## Known Issues:

Firmware Version	Known Issues
V1.00.22	N/A
V1.01.00	1. Safari above 6.1 will not display the video on MAC os.
V1.02.01	1. Export AVI function will not work on MAC OS.
V2.00.11	<p>1. Export AVI function will not work on MAC OS.</p> <p>2. Upgrade to V2.00 , the device will be factory default.</p> <p>3. Don't support windows area of motion setting.</p>
V2.01.01	<p>2. Export AVI function will not work on MAC OS.</p> <p>3. Don't support windows area of motion setting.</p>
V2.01.03	<p>1. Export AVI function will not work on MAC OS.</p> <p>2. UDon't support windows area of motion setting.</p>
V2.01.04	<p>1. Export AVI function will not work on MAC OS.</p> <p>2. Don't support windows area of motion setting.</p>
V2.02.00	<p>1. Export AVI function will not work on MAC OS.</p> <p>2. Don't support windows area of motion setting.</p>

## Related Documentation:

N/A