



Software Version: 2.0.25
Prom Code Version: 5.3.0
Published Date: 2017/03/15

Content:

Revision History and System Requirement:	2
New Features:	2
Problems Fixed:	2
Known Issues:	2
Related Documentation:	2
Note:	Error! Bookmark not defined.

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
DP V2.0.25	2017/03/15	DNR-322L/326 v2.4	N/A

New Features:

Firmware Version	New Features
DP V2.0.25	1. New Camera Support: DCS-2530L

Problems Fixed:

Firmware Version	Problems Fixed
DP V2.0.25	1. Fixing DCS-960L Audio Noise issue for TCP/UDP connection

Known Issues:

Firmware Version	Known Issues
DP V2.0.25	1. DCS-2530L <ul style="list-style-type: none"> i. The camera PTZ function might not work normally when using RS-485(camera firmware issue) ii. Alarm I/O cannot work normally(camera firmware issue) iii. Video parameter sometime cannot be retrieved normally(camera firmware issue)

Related Documentation:

P.S. Device Pack V2.0.x only allows to be installed in DNR-322L (HW:A) V2.4 FW