

DSL-2540B Firmware Release Notes

Firmware: E5.2T02-4-DL-R1B081-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2011/10/28

Problem Resolved:

1. add Dynamic DNS function.

Enhancement:

None

Known Issues:

None

Firmware: E5.2T02-4-DL-R1B080-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2011/6/9

Problem Resolved:

Enhancement:

change softwareversion :NA_1.00

Known Issues:

None

Firmware: E5.2T02-4-DL-R1B060-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2011/1/14

Problem Resolved:

1. IPTV change channel slowly with Route Mode
2. Not support IGMPV3 now

Enhancement:

Known Issues:

Firmware: E5.2T02-4-DL-R1B051-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2010/11/30

Problem Resolved:

1. Bridge Mode Security Test, PC B can't ping to DUT and open Web UI.
2. Change the Version Info.
3. DUT can't setting the filtering rule which has 0 in IP address as source destination.
4. Unauthorized user can reboot DUT from WAN and LAN side.
5. DUT WAN interface can't send RIP version2 packets.
6. Use chrome can't upload backup file to DUT in Windows XP environment.
7. BT problems.

Enhancement:

Known Issues:

None

Firmware: E5.2T02-4-DL-R1B040-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2010/06/07

Problem Resolved:

1. Don't allow the DUT to be the DMZ host.

Enhancement:

1. Add RIP function.
2. Add auto scan PVC function.

Known Issues:

None

Firmware: E5.2T02-4-DL-R1B020-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2010/03/16

Problem Resolved:

2. Don't allow the DUT to be the DMZ host.

Enhancement:

3. Add RIP function.

Known Issues:

None

Firmware: E5.2T02-4-DL-R1B012-DNA.EN

Hardware: DSL699E5.2T02-4

Date: 2010/01/11

First Release

Known Issues:

None