

DSR-1000AC Firmware Hotfix Release Notes

Firmware: v3.19.B101H Hotfix

Hardware: Ax

Date: 11/14/2022

3rd Party Report:

Alex.Shang

Dawn Security Lab, JD dot com Inc

Blog: dawnslab dot jd dot com

Email : ext dot shangalex1 at jd dot com

Problems Resolved:

Hotfix firmware for the vulnerability:

BUG1: SQL Injection when login

BUG2: Command Injection after authentication

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.

D-Link Corporation
