



DSR-250N Firmware Hotfix Release Notes

Firmware: 3.17B401C_RU Hotfix

Hardware: Cx

Date: December 1, 2020

Overview:

On August 11, 2020, a 3rd party security researcher submitted a report accusing the DSR-250 Hardware Revision A1 using firmware v3.17 or older (2) Authenticated remote command execution (1) unauthenticated vulnerabilities. Since this product shares firmware with other models in the DSR Family, DSR-150 / DSR-250 / DSR-500 / DSR-1000AC will require updates to patch these issues.

For more information, visit:

<https://supportannouncement.us.dlink.com/announcement/publication.aspx?name=SAP10195>

Problems Resolved:

- Unauthenticated Remote LAN/WAN Root Command Injection
- Authenticated Root Command Injection

3rd Party Report:

Digital Defense, Inc. Vulnerability Research Team

Coordination: Samuel Shapiro:: VulnerabilityResearch_at_digitaldefense_dot_com

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.