

DWA-182 Firmware Release Note

Firmware: v3.02b05

Hardware: C1

Date: 18, Mar,2014

XP/XP64: 1024.9.1219.2013

Vista/Vista-64: 1024.9.1219.2013

Win7/Win7-64: 1024.9.1219.2013

Win8/Win8-64: 1024.9.1219.2013

Win8.1/Win8-64: 1026.4.1023.2013

Problems Resolved:

Fix Wizard incorrect page information.

- (1) When changing USB mode, the connection will be re-connected.
- (2) When changing USB mode, the utility will disappear during 10s-15s.
- (3) XP/XP64 do not support utility, so users can't use the utility to create the WPS connection.
- (4) Win8 remove hardware icon might be disappear.
- (5) When the security is Shared key, the configuration of Utility profile is not accordant.

Enhancements:

1. NA
-