



DAP-1360 Firmware Release Notes

DAP-1360 Revision A Release Notes

=====

Firmware: 1.10

Date: 02/02/11

1. Add DHCP enhance "always broadcast" function in lan.htm.
2. Fix throught the wizard to finish a WEP Open connection then back to the setting page, the security mode is WEP Shared. The issue happened in both AP-Client mode and Repeater mode issue, add "auto" option.
3. Fix the blackberry 9700 ping lose issue.
4. Add SMAC function.
5. Fix user can't make a WPS connection in repeater mode.
6. Fix the WPA2-PSK function is not working in repeater mode.
7. Fix the bug about input empty password can not login before input error password in login page.
8. Fix backup mode IP to 192.168.0.50.
9. Fix backup mode MAC address same as normal mode.
10. Fix the st_device.htm page about do not showing Default Gateway in WISP mode.
11. Fix the lan.htm page about checking current IP and default gateway to be the same subnet.
12. Fix lan.htm page error string.
13. This version has been updated a new wireless driver and with D-Link changes the version number.

=====