



DAP-1520 Firmware Release Notes

Firmware: FW v1.02

Hardware: Rev. Ax

Date: 2013/03/31

Problems Resolved:

Firmware upgrade notification will now no longer keeps asking user to upgrade same firmware over and over again.

Enhancements:

Default management UI URL changed to "dlinkapWXYZ" for unique access among all the D-Link AP devices in the network.

Enhance WPS-PBC process timing.

Enhance Wi-Fi extending compatibility.

Know Issues:

None

----- END -----