



DAP-1520 Firmware Release Notes

Firmware: FW1.05.B02 (Release)

Hardware: A1

Date: 2013/05/19

Note:

None

Problems Resolved:

1. Firmware upgrade notification will no longer prompt user to upgrade the same firmware repeatedly.

Enhancements:

1. Default management UI URL changed to "dlinkapWXYZ" for unique access among all the D-Link AP devices in the network.
2. Enhance WPS-PBC process timing.
3. Enhance Wi-Fi extending compatibility.

Known Issues:

None
