



Firmware Version: V1.04-4520
Prom Code Version:
Published Date: 2010/Dec./02

Content:

Revision History and System Requirement:	2
Upgrading Instructions:	2
Upgrading by using Web-UI	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.03-4108	2010/Apr./15	DCS-1100(L) DCS-1130(L)	A1
V1.04-4520	2010/Dec./02	DCS-1100(L) DCS-1130(L)	A1 A2

Upgrading Instructions:

Upgrading by using Web-UI

New Features:

Fireware Version	New Features
V1.03-4108	Enhancement <ol style="list-style-type: none"> 1. Modify "Security" graph to "Surveillance" wording graph. 2. Update copyright statement of web pages. 3. Update system check boot-up date/time and restore factory default date/time to 2010/01/01. 4. Remove 2009 select item of manually date/time settings.
V1.04-4520	<ol style="list-style-type: none"> 1. syncing device time when running setup wizard.

Problems Fixed:

Firmware Version	Problems Fixed
V1.03-4108	<ol style="list-style-type: none"> 1. Improvement RTSP compatibility with BlackBerry mobile phone. 2. Fo r DCS-1100 and DCS-1130, fixes some MAC address lead UPnP failure. 3. For DCS-1100 and DCS-1130, remove useless code cause incorrect IR icon on Live View web page.

V1.04-4520	1. fixed firmware upgrade fail issue. 2. fixed DHCP/PPPoE fail for setup wizard.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A