

DCS-1100L/1130L Firmware Release Note

Version: 1.06-7829

Date: May 29, 2013

SVN Revision: 24290

Problems Resolved:

1. Base on ver 1.05-5829, upgrade firmware naming to ver 1.06.
2. Fix security vulnerability issues from CoreSecurity.
3. Enable RTSP authentication as default.

Version: 1.05-5829

Date: September 29, 2011

SVN Revision: 24004

Problems Resolved:

1. Fix video clip's mail bugs.

Version: 1.05-5731

Date: Aug. 31, 2011

SVN Revision: 23991

Problems Resolved:

1. Fix BTS bugs.

Enhancements:

1. Support IE9.
2. Privacy mode audio volume set to 0.
3. update mydlink agent to 2.0.08-201108261817.

Version: 1.05-5522

Date: June 22, 2011

SVN Revision: 23706

Problems Resolved:

- 1, fix compatibility bug between camera and D-ViewCam.
- 2, fix NIPCA bugs.
- 3, other Firmware and web UI bugs.

Version: 1.05-5301

Date: April 1, 2011

SVN Revision: 23333

Problems Resolved:**Enhancements:**

1, update mydlink to 2.0.03-201103301737.

Note:

Dose not support IE 9.

Version: 1.05-5224

Date: March 24, 2011

SVN Revision: 23279

Problems Resolved:**Enhancements:**

1, update dlink 2.0 packages to 2. 0. 03-201103231200.

Note:

Dose not support IE 9.

Version: 1.05-5223

Date: March 23, 2011

SVN Revision: 23253

Problems Resolved:

- 1, HTTPS with IE6 bug.
- 2, Refine for NIPCA.
- 3, Other web UI bugs.

Enhancements:

1, update dlink 2.0 packages to 2. 0. 02-201103211002.

Note:

Dose not support IE 9.

Version: 1.05-5124

Date: February 24, 2011

SVN Revision: 22891

Problems Resolved:

- 1, Refine mydlink agent executable
- 2, Updated ActiveX(version: 1,0,0,4824--> 1,0,0,5118) for the newer Digital Signature
- 3, fixed NIPCA 1.9.3 bugs

Enhancements:

Note:

Version: 1.05-5116

Date: February 16, 2011

SVN Revision: 22789

Problems Resolved:

- 1, Web UI issues.

Enhancements:

- 1, update dlink 1.5 packages to 2.0.00-201101271753.

Note:

Version: 1.05-5030

Date: January 30, 2011

SVN Revision: 22698

Problems Resolved:

- 1, Add tls/ssl and starttls to mail of recording
- 2, snapshot buf on None-IE browser
- 3, live video bugs on Firefox
- 4, Web UI bugs

Enhancements:

- 1, Wording issue

Note:

Version: 1.05-5017

Date: January 17, 2011

SVN Revision: 22546

Problems Resolved:

- 1, Hide https pages and help information
- 2, fix ftp bugs
- 3, fix the Live Video page will appear the "SD Card" description

Enhancements:

Note:

Version: 1.05-5007

Date: January 7, 2011

SVN Revision: 22491

Problems Resolved:

- 1, Snapshot ftp reconnect bug
- 2, Enable Event Based Motion Detection with Schedule, the Event Based Motion Detection can not send FTP image.
- 3, Motion Detection recording to SD Card endurance test fail.
- 3, Https system log.
- 4, Remove the Offset is -xx:xx for Daylight Saving Time setting.

Enhancements:

Note:

update dlink 1.5 packages to 1.3.10-201012201339

Version: 1.05-4915

Date: December 15, 2010

SVN Revision: 22313

Problems Resolved:

Enhancements:

Added 10sec waiting time for motion detection setup wizard apply.

Note:

Version: 1.05-4913

Date: December 13, 2010

SVN Revision: 22271

Problems Resolved:

1. smtp ssl/tls and starttls hints/help information

Enhancements:

Note:

Version: 1.05-4906

Date: December 6, 2010

SVN Revision: 22199

Problems Resolved:

2. add https description
3. modify help information
4. modify for auth control direct view streaming

Enhancements:

1. refine JPEG getter example

Note:

Version: 1.05-4830

Date: November 30, 2010

SVN Revision: 22155

Problems Resolved:

5. Fix when prefix filename is max, then send mail error.
6. change link from [support.dlink.com.tw] to [support.dlink.com].

Enhancements:

2. modify progress times
3. Refine check pppoe user name length

Note:

Version: 1.05-4819

Date: Nov. 19, 2010

SVN Revision: 22005

Added:

7. HTTPS function.
8. Privacy Mask function.
9. Video Clip function.
10. SMTP over TLS/STARTTLS.

Modified:

1. Recording function removed.

Enhancements:

1. Update D-Link 1.5 to 1.3.6-201011081645.

Note:

1. Please processing [Restore Factory Defaults] after upgrade firmware to make the modifications and new function affect

Version: 1.04-4520

Date: August 20, 2010

SVN Revision: 20939

Enhancements:

2. Update D-Link 1.5 to 1.50-201008181107.

Version: 1.04-4511

Date: August 11, 2010

SVN Revision: 20773

Enhancements:

3. Update D-Link 1.5 to 1.50-201007281745.

Version: 1.03-4102

Date: April 02, 2010

SVN Revision: 18600

Note:

Please processing “Restore Factory Defaults” after upgrade firmware to make the modifications and new function affect.

Enhancements:

1. Update D-Link 1.5 to 1.50-201004021510.

Version: 1.03-4026

Date: March 26, 2010

SVN Revision: 18525

Note:

- 1. First release of DCS-1100L/1130L.**
- 2. Please processing “Restore Factory Defaults” after upgrade firmware to make the modifications and new function affect.**

Enhancements:

1. Update D-Link 1.5 to 1.50-201003231747.
2. Add video clip to FTP function via API for mydlink integration.
3. Modify "Security" graph to "Surveillance" wording graph.
4. Apply up-to-date mobile web pages.
5. Update copyright statement of web pages.
6. Update system check boot-up date/time and restore factory default date/time to 2010/01/01.
7. Remove 2009 select item of manually date/time settings.

Problems Resolved:

1. Improvement RTSP compatibility with BlackBerry mobile phone.