



Firmware Version: V1.02.00
Prom Code Version:
Published Date: 2013/7/29

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.02.00	2013/7/29	DCS-2132L	A1
V1.01.10	2013/6/18	DCS-2132L	A1
V1.00.06	2012/8/27	DCS-2132L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.02.00	<ol style="list-style-type: none">1. Update the mydlink agent to 2.0.17-b18 .2. Support 2-way audio function at portal and APP3. Support onvif test tool V12.064. Enhancements the low light image.
V1.01.10	<p>The Firmware is only supported by wizard v1.04.02 or above.</p> <ol style="list-style-type: none">1. Upgrade to UPnP v1.6.18.2. Remove the default account "guest"3. RTSP Authentication is default enable.
V1.00.06	Initial version.

Problems Fixed:

Firmware Version	Problems Fixed
V1.02.00	<ol style="list-style-type: none">1. Fix overexposure bug2. Fixed the IPV6 Enable and change the http port the web server will crash.
V1.01.10	<ol style="list-style-type: none">1. Remove the default account "guest".2. RTSP Authentication is default enable.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A