



Firmware Version: V2.10.11
Prom Code Version:
Published Date: 2015/8/17

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.10.11	2015/8/17	DCS-2132L	B1
V2.02.05	2015/1/15	DCS-2132L	B1
V2.01.06	2014/5/23	DCS-2132L	B1
V2.00.05	2014/2/17	DCS-2132L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V2.10.11	1. Update agent to 2.0.19b51
V2.02.05	<ol style="list-style-type: none"> 1. Update agent to 2.0.18b09 2. Disabled SSL 3.0, RC4/DES to fix security hole 3. Added language autodetection 4. Add support for Motion detection, direct MJPEG decoding, and Privacy masks on non-IE browsers 5. Add 50MB/30 sec Event on SD function 6. Add 720P resolution for profile 2 7. Add Bonjour Name function 8. Enhance the Wi-Fi stability 9. Added new DDNS selection.
V2.01.06	<ol style="list-style-type: none"> 1. Change Agent version to 2.0.17-b59. 2. Support 2-way audio on App 3. Support playback on App 4. Set passive mode enable of FTP as default
V2.00.05	1 st version for new H/W solution, B1 version

Problems Fixed:

Firmware Version	Problems Fixed

V2.10.11	<ol style="list-style-type: none"> 1. Fixed the Cross-Site Scripting(XSS) issue 2. Fixed the security issue of tunneling RTSP streaming over HTTP 3. Disable SSH connection
V2.02.05	<ol style="list-style-type: none"> 1. Remove the PSIA protocol which allowed getting the snapshot without authentication. 2. Fixed the issue that the certificate on the camera wouldn't be reset after factory reset. 3. Fixed the issue that after performing the endurance test, camera would stop uploading snapshots to SMB when periodic trigger is set. 4. Fixed the issue of image with green tone in some case. 5. Fixed the issue of access permission configured on Access List. 6. Revised Helpful Hints for clarity.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A