



Firmware Version: V1.11.00
Prom Code Version:
Published Date: 2015/10/1

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.11.00	2015/10/1	DCS-5029L	A1
V1.10.07	2015/8/17	DCS-5029L	A1
V1.02.00	2015/1/9	DCS-5029L	A1
V1.01.04	2014/11/12	DCS-5029L	A1
V1.00.04	2014/6/16	DCS-5029L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.11.00	<ol style="list-style-type: none"> 1. Updated Digital Signature 2. Updated agent to 2.0.19b51n
V1.10.07	<ol style="list-style-type: none"> 3. Update agent to 2.0.19b51
V1.02.00	<ol style="list-style-type: none"> 1. Update agent to 2.0.18b43 2. Security Enhancements
V1.01.04	<ol style="list-style-type: none"> 1. Update agent to 2.0.18b09 2. Add 50MB/30 sec Event on SD function 3. Add 720P resolution for profile 2 4. Add support for Motion detection, direct MJPEG decoding, and Privacy masks on non-IE browsers 5. Add new DDNS selection 6. Changed display model to DCS-5222L B (no number designator) 7. Changed default timer from 60 to 90s 8. Add Default UI language detection 9. Updated Wi-fi drivers to comply with latest EU ECN 300 328 requirements

Problems Fixed:

Firmware Version	Problems Fixed
V1.10.07	<ol style="list-style-type: none"> 1. Fixed the Cross-Site Scripting(XSS) issue 2. Fixed the security issue of tunneling RTSP streaming over HTTP 3. Disable SSH connection
V1.02.00	<ol style="list-style-type: none"> 1. Fixed issue where device would not default to English language when unsupported language was detected 2. Removed deactivated PSIA protocol that was causing conflicts
V1.01.04	Fixed iOS PT issues.
V1.00.04	Initial Release

Known Issues:

Firmware Version	Known Issues
V1.02.00	Due to updated security settings, initial plugin supplied at release will require a workaround to view on Safari 8. This is not a Firmware issue, however is listed with this version since this is the first firmware tested that was affected.
V1.00.04	Firmware does not follow 6-30 character password rules

Related Documentation:

N/A