



**Firmware Version:** V2.03.01  
**Prom Code Version:**  
**Published Date:** 2015/1/6

---

**Content:**

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed: .....	3
Known Issues: .....	3
Related Documentation: .....	3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.03.01	2015/1/6	DCS-5222L	B
V2.02.06	2014/11/13	DCS-5222L	B
V2.01.05	2014/5/14	DCS-5222L	B1
V2.00.05	2014/1/21	DCS-5222L	B1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V2.03.01	<ol style="list-style-type: none"> <li>1. Security Enhancements</li> <li>2. Korean Language Support</li> </ol>
V2.02.06	<ol style="list-style-type: none"> <li>3. Update agent to 2.0.18b09</li> <li>4. Add 50MB/30 sec Event on SD function</li> <li>5. Add 720P resolution for profile 2</li> <li>6. Add support for Motion detection, direct MJPEG decoding, and Privacy masks on non-IE browsers</li> <li>7. Add new DDNS selection</li> <li>8. Changed display model to DCS-5222L B (no number designator)</li> <li>9. Changed default timer from 60 to 90s</li> <li>10. Add Default UI language detection</li> <li>11. Updated Wi-fi drivers to comply with latest EU ECN 300 328 requirements</li> </ol>
V2.01.05	<ol style="list-style-type: none"> <li>1. Change Agent version to 2.0.17-b59.</li> <li>2. Support 2-way audio on App</li> <li>3. Support playback on App</li> </ol>
V2.00.05	1 <sup>st</sup> version for new H/W solution, B1 version

## Problems Fixed:

Firmware Version	Problems Fixed
V2.03.01	<ol style="list-style-type: none"> <li>1. Fixed issue where device would not default to English language when unsupported language was detected</li> <li>2. Removed deactivated PSIA protocol that was causing conflicts.</li> </ol>
V2.02.06	<ol style="list-style-type: none"> <li>3. Fixed issue where device add incorrect date and time suffix when emailing detection snapshots.</li> <li>4. Fixed various mydlink PTZ compatibility issues with iOS and DviewCam</li> <li>5. Fixed issue where ICR would open despite being over 30 lux</li> <li>6. Fixed m-packet issues</li> <li>7. Revised Helpful Hints for clarity.</li> </ol>
V2.01.05	<ol style="list-style-type: none"> <li>1. Fixed the MP4 files can't download from mydlinklite APP.</li> <li>2. No OSD data/time text on 480p live view in mydlink portal.</li> <li>3. The PTZ function goes opposite direction on mydlink portal/App/GUI if the "Filp"/"Mirror" option is enabled.</li> </ol>

## Known Issues:

Firmware Version	Known Issues
V2.03.01	Due to updated security settings on Safari 8, users will need to change security to view camera on Safari 8.

## Related Documentation:

N/A