



Firmware Version: V1.01.03

Prom Code Version:

Published Date: 2015/6/15

Content:

New Features:	. 2
Problems Fixed:	. 2
Known Issues:	. 3
Related Documentation:	. 3
Upgrading Instructions:	. 3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01.03	2015/6/15	DCS-855L	A1
V1.00_4312	2014/10/14	DCS-855L	A1

New Features:

Firmware Version	New Features			
	Update mydlink Agent to 2.0.19-B05			
	Support UTF-8 Unicode format for SD card music playback.			
	 Support new Bonjour service type "_dcameratcp". 			
	 Change the default system time for year 2015. 			
	Refine the firmware version naming definition.			
V1.01.03	 Remove all web-pages, except RAM page. 			
	Lower the Day/Night mode switching threshold after firmware upgrade.			
	 Update the time zone table for Russia and Chile. 			
	Recording file naming supports multi events.			
	Remove Bonjour server of "_httptcp" .			
	Shorten the flash writing interval from 30 seconds to 10 seconds.			
V1.00_4312	1 st version			

Problems Fixed:

Firmware Version	Problems Fixed				
	Fix the POODLE security vulnerability by disable SSLv3.				
	Fix following vulnerabilities of Onward security test.				
_	 OnSec-VUZ-103-48001, TLS/SSL Server Supports Weak Cipher Algorithms 				
	OnSec-VUZ-103-48002, OpenSSL CCS Injection				
V1.01.03	OnSec-VUZ-103-48008, music_stop.cgi Unauthenticated Access				
	OnSec-VUZ-103-48009, sdcard_music_list.cgi Unauthenticated Access				
	OnSec-VUZ-103-48010, sdcard_upload.cgi Unauthenticated Access				
	OnSec-VUZ-103-48011, sys_music_list.cgi Unauthenticated Access				
	OnSec-VUZ-103-48012, sys_music_play.cgi Unauthenticated Access				
V1.00_4312	1 st version				





Known Issues:

Firmware Version	Known Issues
V1.01.03	N/A
V1.00_4312	N/A

Related Documentation:

N/A

Upgrading Instructions:

This camera can only be updated from the mydlink Baby app when a firmware update message appears on the app.

