



**Firmware Version:** V1.07\_b2  
**Prom Code Version:**  
**Published Date:** 2013/12/26

---

**Content:**

Upgrading Instructions:..... 2  
New Features:..... 2  
Problems Fixed: ..... 3  
Known Issues: ..... 3  
Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
v1.07_b2	2013/12/26	DCS-932L	A1
v1.06_b4	2013/2/20	DCS-932L	A1
v1.05_b5	2012/11/19	DCS-932L	A1
v1.04_b5	2012/9/3	DCS-932L	A1

## Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

## New Features:

Firmware Version	New Features
V1.07_b2	<ol style="list-style-type: none"> <li>1. Add schedule feature for motion detection function.</li> <li>2. NTP source port change to port 123</li> <li>3. Add user can configure interval setting for motion detection of mail/ftp.</li> <li>4. User account name is limit as: 0-9, a-z, A-Z, “:”, “-“, “_”.</li> <li>5. Update Mydlink agent to v2.0.17-b31</li> <li>6. Limit “Auto” FTP image frequency not over 5 frames/second.</li> </ol>
V1.06_b4	<p><b>Firmware V1.06_b4 is only supported by wizard v1.02.10 or above.</b></p> <ol style="list-style-type: none"> <li>1. Change maximum admin password length, from 8 characters to 30 characters.</li> <li>2. Change PPPoE retry timing, retry connection on 30 seconds interval till connect.</li> <li>3. New ActiveX to support long admin password.</li> <li>4. Default time change to 2013-01-01</li> <li>5. Change IR LED Night to Day switch timing to 7 seconds.</li> </ol>
V1.05_b5	<ol style="list-style-type: none"> <li>1. Add mydlink agent version displayed on Web UI.</li> <li>2. Update Java program to support new mjpeg streaming format</li> <li>3. Change NTP request timing</li> </ol>
v1.04_b5	<ol style="list-style-type: none"> <li>1. Upgrade new mydlink agent to v2.0.16-b4</li> <li>2. Secure the configuration file with the new changed encryption method.</li> <li>3. Remove two WebGUI Hidden Pages for RD develop using.</li> <li>4. Remove the Telnet Daemon will be activated about 5 seconds when the Device is booting.</li> <li>5. Remove the hidden FTP server.</li> </ol>

## Problems Fixed:

Firmware Version	Problems Fixed
V1.07_b2	<ol style="list-style-type: none"> <li>1. Fixed ip task will be restarted issue on DHCP renew time.</li> <li>2. Fixed E-mail/FTP cannot be started issue if motion detection is enabled first.</li> <li>3. Fixed UpnP issue with DIR-826L router</li> <li>4. The max length of Admin password change to 32 characters</li> </ol>
V1.05_b5	<ol style="list-style-type: none"> <li>1. Fixed ios6 live view hang issue – modify mjpeg streaming format</li> <li>2. Fixed sometimes startup java view failed on Win 7 + IE9</li> <li>3. Fixed live view issue if http port is changed to 12345.</li> <li>4. Fixed live view streaming cannot pass through router’s virtual server.</li> <li>5. Fixed e-mail loss issue when live view the camera.</li> </ol>
v1.04_b5	<ol style="list-style-type: none"> <li>1. Fixed the live stream can’t display when using the https connection.</li> <li>2. Fixed bad audio streaming on 3G internet access.</li> </ol>

## Known Issues:

Firmware Version	Known Issues

## Related Documentation:

N/A