

DCS-942L Firmware Release Notes

Firmware Version: 1.01-0902_WW

Release Date: 2011-11/B.

Hardware Version: A1

New Features:

1. Support SD Recoding-allows user to configure and scheduling the recording of your camera and can record video to the local SD card.
2. Support SD Management- user could browse and manage the record files which store in SD card.

Problems Resolved:

1. Correct issue of WPS cannot associate successfully after reboot.
2. Update mydlink to v2.0.09-201110141349.
3. Fix bugs in Redmine.
4. Fix bugs in Alpha BTS.
5. ICR light sensor sensitivity (3 seconds).
6. PIR fix with ICR switch current.
7. wireless throughput drop-off.

Enhancements:

1. Support SD recording and SD Management

Note:

- A. Move Snapshot to SD function from snapshot UI to Recording UI.
- B. Remove VideoClip to SD.
- C. Support Individual Ignore motion time to FTP and SMTP in both snapshot/videoclip web page, and rename “Ignore Following Motions” to “Send next FTP after”/” Send next e-mail after”. furthermore, the range has been changed.

Known Issues:

None

Firmware: v1.00_0522

Hardware:

Date: 2011-8/B

First release

Problems Resolved:

None

Enhancements:

None

Known Issues:

None