

=====

DGL-5500 Revision A Release Notes

=====

Firmware 1.12B05
Date: 06/24/2014

1. Fix Inbound filter rules display error
2. Fix the issue that DUT cannot set virtual server rules with equal destination ports in virtual server.
3. Fix Wake-on-LAN issue

=====

DGL-5500 Revision A Release Notes

=====

Firmware 1.11B03
Date: 10/25/2013

- Updated wireless drivers (v10.1.4362) to improve wireless performance
- 1- Firmware support for saving settings without the need for rebooting
- 2- Fixed issue with QRS mobile in iOS7
- 3- Addressed issue with bookmarking from the setup wizard in Chrome
- 4- Fixed issue with MAC and Website filter when deleting and adding a new entry
- 5- Fixed "internal error" message when clearing and saving logs
- 6- Fixed bugs related to WPS-PIN; LED not blinking
- 7- Fixed bug related to inbound filter rule
- 8- Fixed issues related to Filter, Access Control and Add Policy
- 9- Fixed "pop up" message appearing even without any changes to the page
- 10- Fixed issue with accessing the USB port using Samba
- 11- Fixed functionality of "Restore" button when setting back to factory default.

=====

DGL-5500 Revision A Release Notes

=====

Firmware 1.10B04
Date: 09/4/2013

Release Notes:

Problems Resolved & Enhancements:

1. Fixed: Browser Compatibility for:
 - http://dlinkrouter.local
 - http://192.168.0.1
 - using QRS Mobile
2. Fixed: Formatting in DHCP table
3. Fixed: Updated WLAN Driver for stability
4. Fixed: ACL rule can be deleted

5. Fixed: MAC Filtering can On/Off even if rules exist
6. Fixed: MAC Filtering config requiring reboot
7. Added: Syslog under Status->Logs
8. Added: Dynamic DNS under Advanced->DMZ
9. Added: 5GHz Bursting as Default Enabled
10. Added: WPS-PIN/PBC (for Win8.1 Logo, WPS logo)
11. Added: Auto 20/40Mhz 2.4GHz Co-existence
12. Performance Tuning: LAN-WAN QOS
13. Performance Tuning: 'my network map'
14. Improved: MAC Filtering GUI Table formatting
15. Improved: Inc. to 25 entries/page in Log
16. Improved: Setup wizard bandwidth testing
17. Improved: GUI Layout and Graphics
18. Improved: Factory Default Setup Wizard behavior
19. Improved: Web GUI for setting wireless encryption method
20. Improved: User feedback messages
 - Page return flow when press cancel
 - Add Ok button to 'Warning' messages
 - Prompt saving setting when press cancel
 - Prompt saving when user abandons page
22. Improved: Correct DHCP Reservation Table Labels
23. Improved: Correct DHCP Reservation IP management
24. Improved: Correct DHCP Reservation GUI Button Improvements
25. Remove: "802.11b only" mode in 2.4GHz.
26. Remove: Guest field in wireless status page.

=====