



## **DGS-3000-Series Firmware Patch Notes**

**Firmware: 4.00B023 BETA**

**Hardware: Bx**

**Date: November 7, 2018**

### **Problems Resolved:**

1. IP Path MTU Discovery
  2. DHCP packet forward issue
  3. Incorrect temperature in log
-