



DIR-1950 Firmware Hotfix Release Notes

Firmware: 1.13B01_BETA4_HOTFIX

Hardware Revision: Ax

Date: February 22, 2022

Brief:

MediaTek Vulnerabilities - Wi-Fi WPS/IEEE-1905 BadMesher & Authentication Flooding

1. Link - <https://www.blackhat.com/eu-21/briefings/schedule/#badmesher-new-attack-surfaces-of-wi-fi-mesh-network-24181>
2. Link - <https://www.tenable.com/cve/CVE-2021-41788>

Problem Resolved:

- CVE-2021-35055
- CVE-2021-37560
- CVE-2021-37561
- CVE-2021-37584
- CVE-2021-37563
- CVE-2021-32467
- CVE-2021-32468
- CVE-2021-32469
- CVE-2021-37562
- CVE-2021-41788

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.