



DIR-2660 A1 Firmware Release Note

Firmware: v1.01B03

Hardware: A1

Date: March 30, 2019

Problems Resolved:

1. Fixed the problem that the wizard configuration can't modify the wireless parameters to synchronize to Mesh AP
2. Fixed the problem that only one U disk can be identified after the USB2.0 and USB3.0 are plugged in and the device is restarted at the same time.
3. Fixed Multicast Failure at Dynamic IPv6 Address Mode
4. Fixed Wi-Fi Mesh sync up failed when using D-Link Wi-Fi app

Enhancements:

None

Known Issues:

None
