



DIR-3040 Firmware Hotfix Release Notes

Firmware: 1.20B03 Hotfix

Hardware Revision: Ax

Date: September 22, 2021

3rd Party Report:

The following report has been submitted from Cisco Talos.
Cisco Talos - vulndiscovery at external dot cisco dot com
Regina Wilson - (regiwils) regiwils at cisco dot com

Problems Resolved:

- CVE-2021-21913 – Smart Mesh information disclosure vulnerability

Known Issues:

This firmware patch will no longer be compatible with DAP-1620-EXO (Rev B) or DAP-1820 (revA) range extenders due to the fixes implemented in this patch.

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.