

DIR-813 Firmware Release Notes

Firmware: FW v2.09B08

Hardware: Rev. Ax

Date: 2016/05/09

Note:

1. The firmware version is advanced to v2.09.

Problems Resolved:

1. Fixed the ping lose issue.
2. Fixed the issue that the router can't disconnect when it reaches the idle time in PPTP/L2TP on-demand mode.
3. Fixed the packet leakage issue.
4. Fixed the issue that NTP server can't update sometimes.
5. Fixed the issue that DWA-182C & DWA-171 WPS may fail to connect to DIR-813 when enable 5G or 2.4G wireless only
6. Fixed the issue that DNS will be change to "Manual DNS" if home user sets INTERNET connection type to Static IP.
7. Fixed the issue that wireless client can't connect to DIR-809 via WPS if 2.4G WPS or 5G WPS is enabled in wireless security setting.
8. Fixed the UI issue in easy setup page.
9. Fixed the country code issue.
10. Fixed the issue that UI flow sometimes may freeze during the flow of easy setup page.
14. Fixed the issue that when MAC filter is enabled, the router can't access network in specific IP range.
15. Fixed the issue that sometimes the download speed setting may not work in traffic control feature.
16. Fixed the issue that when home user disables 5G wireless function, then change wireless security from TKIP to AES, in DIR-813, DIR-813 may crash and reboot while connecting via WPS .
17. Fixed UI issues in displaying firmware version.
18. Fixed IPv6 neighborhood issue.
19. Fixed the issue that Sony Xperia C5 Ultra E5506 can get DHCP IP from DIR-813. and INTERNET while executing ping command.

Enhancements:

1. Improved 5G wireless throughput

Known Issues:

None
