



## DIR-822 Firmware Release Notes

**Firmware: FW v3.01B02**

**Hardware: Rev. Cx**

**Data: 2016/4/27**

### **Problem Resolved:**

- Fixed Security Vulnerability: Stack-based buffer overflow exploit - CVE-2016-5681 VU#332115
  - Reported by Daniel Romero - NCC Group - Street: Calle Serrano Galvache Number: 56 Building: Abedul Floor: 4th, Madrid, 28033

For additional details please visit: <http://supportannouncement.us.dlink.com/announcement/publication.aspx?name=SAP10063>

### **Enhancements:**

- Enhance wireless performance in interference environment.
-