



DIR-822 Firmware Release Notes

Firmware: FW v3.02

Hardware: Rev. Cx

Data:2017/9/14

Problem Resolved:

- Fix can't enter website URL with hyphen(-).
- Fix IGMP problem.

Enhancements:

- Supports VLAN feature.
- Supports NAT loopback

----- END -----