



DIR-822 Firmware Release Notes

Firmware: 3.15B02 WW

Hardware: Rev. Cx

Date: November 6, 2019

Note:

- The firmware version is advanced to v3.15.
- The firmware v3.15 must be upgraded from the transitional version of firmware v303WWb04_middle.

Problem Resolved:

- Fix DHCP renew issue.

Enhancements:

- Force setup admin password during wizard setup flow.
-