



DIR-822 Firmware Release Notes

Firmware: FW v3.12B04

Hardware: Rev. Cx

Data: April 26, 2019

Note:

- The firmware version is advanced to v3.12.
- The firmware v3.12 must be upgraded from the transitional version of firmware v303WWb04_middle (only if you currently have firmware lower than version 3.10).

Problem Resolved:

- HNAP Vulnerabilities.
- Can't open Yahoo webpage and Hinet mailbox.
- 2.4G wireless unstable issue.

Know Issue:

- Please don't enable/disable firewall function when CPU busy for BT download.
-