

DIR-822 Firmware Release Notes

Firmware: FW v3.13

Hardware: Rev. Cx

Data:2019/7/10

Note:

- The firmware version is advanced to v3.13.
- The firmware v3.13 must be upgraded from the transitional version of firmware v303WWb04_middle.

Problem Resolved:

- Solve BT issue.
-