

DIR-842 Firmware Release Notes

Firmware: FW v3.11 Hardware: Rev. Cx Data:2019/07/4

Note:

- The firmware version is advanced to v3.11.
- The firmware v3.11 must be upgraded from the transitional version of firmware v3.02b03_middle.

Problem Resolved:

• Modify max length to 64 for server IP address of L2TP.

Enhancements:

- Support FOTA.
- Support MOD