



## **DIR-850L Firmware Release Notes**

**Firmware: FW2.02.B06 (Release)**

**Hardware: B1**

**Date: 2014/11/04**

**Note:**

None

**Problems Resolved:**

1. Update new GUI version
2. Modify routing table for HW NAT
3. Change DHCP reservation's behavior
4. Add 20/40 coexistence

**Enhancements:**

1. Update mydlink agent for https connection
2. Update frequency table

**Known Issues:**

None

---