

DIR-878 Firmware Release Notes

Firmware: FW1.10B05

Hardware: Rev. Ax

Release Date: March 9, 2018

Note:

1. The firmware version is advanced to v1.10
2. The firmware v1.10 must be upgraded from the transitional version of firmware v1.04 (transitional version).

Problems Resolved:

1. Update wpa2 security patch (KRACK)
2. Supports EU VLAN @ EU country code
3. Supports VLAN profile @ SG country code
4. Upgrade dnsmasq to 2.78

Enhancements

1. Supports D-Link Wi-Fi app
(QRS mobile won't be supported from firmware version v1.10 or later version)
 2. Support firmware image with encryption
-