



## **DIR-878 Firmware Release Notes**

**Firmware: 1.20B03 Hot Fix**

**Hardware: Ax**

**Date: June 21, 2019**

**Problems Resolved:**

1. Router DNS Cache Poisoning Caused by Infrastructure Protocol Vulnerabilities

**Reported by:**

GeekPwn (committee at geekpwn dot org)

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.