



## **DIR-878 Firmware Hotfix Release Notes**

**Firmware: 1.30B08\_fix\_buffer\_overflow Hotfix**

**Hardware Revision: Ax**

**Date: March 29, 2021**

### **Problems Resolved:**

- Buffer Overflow Vulnerability

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.