



DAP-1525 Firmware Release Note

Firmware: v1.01

Hardware: A1

Problems Resolved:

1. Disable Guest zone by default.
2. Guest zone access cannot access Router UI