

## **DAP-1610 Firmware Release Notes**

**Firmware: 1.02B02**

**Hardware: A1**

**Date: 2018/01/24**

### **Problems Resolved:**

- Fix DFS band issue.

### **Enhancements:**

- None

### **Known Issues:**

- The firmware file not yet import encryption.