

DAP-1665 Firmware Release Note

Firmware: v2.03B03

Hardware: B1

Date: Feb 12, 2018

Problems Resolved:

1. Copyright is showing 2016.

Enhancements:

1. Update DNSmasq to version 2.78
2. Add WLAN Partition function
3. Add MAC filtering function
4. WPA2 security enhancement (KRACK)
5. Add firmware protection

Note: Need upgrade from v2.00 to v2.03 via middle FW: v2.02 (upgrade from 2.00 to v2.02 first and then upgrade to v2.03)
