

DAP-1820 A1 Firmware Release Note

Firmware: v1.02B04

Hardware: A1

Date: July 18, 2019

Note:

1. Add AU country code
2. Upgrade D-link WiFi Mesh porting package to v1.05.08 to improve provision time

Problems Resolved:

None

Enhancements:

None

Known Issues:

None
