

DAP-2680 Firmware Release Notes

Firmware: v2.00B08r051

Hardware: 1A1G

Date: Apr 24, 2020

Problems Resolved:

1. [DNC] Syncdevicecfgresult sometimes does not carry the established SSID data in subcfgidmaxacllist.
2. [HQ20190929000002][DNC] if we modify SSID on DAP webGUI after it's managed by DNC, DAP will broadcast modified SSID rather than use the SSID we configure on DNC profile.
3. [HQ20191014000014][DNC] 5GHz radio is enabled even if the status of 5GHz radio is still "off" on profile of Nuclias Connect.
4. [DNC] adjust ip-changed flow.
5. [DNC] Message of IP change & IP field is empty in syslog message related to DHCP
6. [DNC] AP offline issue.
7. [HQ20191126000006][MAC ACL] mac acl does not work when bandsteering enable.
8. [DNC] VLAN Settings did not sync from 5G primary Band.
9. [HQ20191205000006][DNC] Username/Password page is shown just once when the mgmt int is tagged.
10. [HQ20191129000002][DNC] Don't renew their IP address when their "Mgmt" interface is changed to another vlan.
11. [HQ20191230000003][DNC] Nuclias connect would be failed to manage an AP with the msg "error cannot recv manageDevice in managed" when its network profile changes.
12. [HQ20191217000007][DNC] Vlan settings in 5GHz switches between 5GHz 1 and 5GHz 2.
13. [HQ20191206000004][DHCP] DHCP name protection.
14. <Behavior change> Follow the SNR-20190603 to modify DHCP client and Time setting behavior.
15. [Security issue]ZDI-CAN-10082: D-Link DAP-2610 Router login Incorrect Comparison Authentication Bypass Vulnerability
16. [Security issue] CTX-2020-02-01 – Disclosure of Administrative Credentials
17. [Security issue] CTX-2020-02-02 – Administrative Password Disclosure
18. [Security issue] Privilege escalation vulnerability in the cli binary
19. [HQ20191121000011][DNC]Few APs are showing offline in nuclias connect.
20. [HQ20191129000003][DNC]Don't send DHCP Discover when its mgmt vlan was changed.
21. [HQ20200210000007][DNC] Username/Password page does not appear on wireless client even if AP is pingable.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r044

Hardware: 1A1G

Date: Jul 12, 2019

Problems Resolved:

1. [WDS] When root AP's SSID is '2680 2 g',repeater AP can't connect with it by WDS with AP or WDS.
2. [captive portal] Login Page Upload work abnormal
3. [Captive portal] the passcode active time can't choose year later than 2019
4. [CWM] [DBG19060149]: Band steering function does not sync after applying the configuration from DNC server.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r043

Hardware: 1A1G

Date: Jul 5, 2019

Problems Resolved:

1. [CWM]DAA support 256 bytes
2. [CWM]Add ssid integrity detection.
3. [CWM]Support 802.1x.
4. [d-lab: DBG19030339][CWM] It shouldn't display the default wizard after managed by Nuclias Connect
5. [CWM] : In Multi-SSID page, it will show some unexpected SSIDs.
6. [CWM]: In nuclias connect Bandwidth optimization, delete rule fail.
7. [CWM] [DBG19060149]: Band steering function does not sync after applying the configuration from DNC server.
8. [Raspberry test] DUT happened crash issue at 2hr 54min.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r039

Hardware: 1A1G

Date: Feb 26, 2019

Problems Resolved:

1. [WDS CLI]The alert message show error

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r038

Hardware: 1A1G

Date: Feb 21, 2019

Problems Resolved:

1. [D-LAB: DBG19010343] DAP-2680_2.00_Cannot rollback to primary DNS server
2. [D-LAB][DBG19010606 }The community in the trap packet only displays 28 characters while setting it as 29 characters on the DUT.
3. [QOS] the qos can't work for downlink in WDS mode

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r036

Hardware: 1A1G

Date: Jan 16, 2019

Problems Resolved:

1. [Bandwidth Optimization] add 2 rules of Allocate specific and someother will cause speed limit failed
2. [Bandwidth Optimization] add 2 rules and find the allocate specific BW for ssid can't work

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r035

Hardware: 1A1G

Date: Jan 14, 2019

Problems Resolved:

1. [Bandwidth Optimization] add 2 rules of Allocate specific and someother will cause speed limit failed

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r034

Hardware: 1A1G

Date: Jan 11, 2019

Problems Resolved:

1. [WDS]WDS only support WPA2

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r033

Hardware: 1A1G

Date: Jan 10, 2019

Problems Resolved:

1. [status]Device channel show error

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r032

Hardware: 1A1G

Date: Jan 10, 2019

Problems Resolved:

1. [Channel Analyze]The select button miss 5G band

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r031

Hardware: 1A1G

Date: Jan 9, 2019

Problems Resolved:

1. [CWM]: Set Nuclias Connect Setting to disable, save and active. In device information should be show disconnect.
2. [CWM] Client's IPv6 Address show wrong
3. [System] it won't work normally when set long DDNS domain as CWM server access address

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-r030

Hardware: 1A1G

Date: Dec 29, 2018

Problems Resolved:

1. new firmware version request.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc029

Hardware: 1A1G

Date: Dec 21, 2018

Problems Resolved:

1. [cli]User cannot get correct channel from cli in 5G band

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc028

Hardware: 1A1G

Date: Dec 20, 2018

Problems Resolved:

1. [intrusion] wireless intrusion search 2.4G band can't work

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc027

Hardware: 1A1G

Date: Dec 17, 2018

Problems Resolved:

1. [TKIP/AES]TKIP or AES can't save success
2. [captive portal] add passcode will cause the device abnormal
3. [NAP]This function doesn't work
4. [WDS]Some special SSID will cause client wds can't connect to root wds

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc026

Hardware: 1A1G

Date: Dec 13, 2018

Problems Resolved:

5. [wireless]The wireless doesn't boot success
6. [TKIP/AES]TKIP or AES can't save success

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc025

Hardware: 1A1G

Date: Dec 12, 2018

Problems Resolved:

1. [DBG18110060](From d-lab)DAP can not get the IP from DHCP server via WDS tunnel
2. [TKIP/AES]TKIP or AES can't save success
3. [CWM] Client's IPv6 Address show wrong
4. [IPv6]This function doesn't work normal when IPv6 server change address
5. [Upload Configuration File]Click upload will cause web page block
6. [login/password]in the wizard , it can set "space"for password ,and can save successfully . But in the administrator page, "space" is invalid value
7. [WDS+AP]This function doesn't work
8. [intrusion] mark all new access points as valid access points failed
9. [intrusion] mark all new access points as Rogue access points failed
10. [IPv6]The alter message show error
11. [CWM]: Set MSSID's broadcast to disable, it can't take effect.
12. [CWM] [Dashboard/Channel Utilization]: When AP's wireless is off, Channel Utilization chart should

update statistics

13. [NAP]This function doesn't work
14. [filter/wlan partition] "Internal station connection" : guest mode work error.
15. [administrator] if set MDNS is 64 characters, but it can't access
16. [Administrator/ limit IP] If delete the first IP address, The index should be update after save
17. [CWM] [Advanced Settings/Performance] Enable/Disable "Transfer DHCP Offer to Unicast", DUT won't take effect
18. [Advanced/WLAN Patition] Connected STA in guest mode can access STA in Enable and Disable mode
19. [Bandwidth optimization][Dlabcase] Bandwidth optimization issue
20. Add CA, AU, JP CTL power

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc024

Hardware: 1A1G

Date: Nov 23, 2018

Problems Resolved:

1. [HQ20171212000006]D-Track_2017_12_Wrong radius accounting attribute.
2. [mib]MDNS need add to mib
3. [DBG18110060](From d-lab)DAP can not get the IP from DHCP server via WDS tunnel
4. [DBG18110084](From d-lab)some city have the alignment issue in timezone list
5. [DBG18110032][MDNS](From d-lab)after changing the country MDNS not work randomly
6. [DBG18110089][airtime]This function doesn't work normal sometime
7. [DGG18110114][DLAB][suggestion]DUT shall prompt "Invalid MAC" only rather than "Plz don't not input multicast case address"
8. [DBG18110085][D-LAB][time and date] In the IE browser, copy PC's Time can't successfully When change the time of PC for Continuous Second Modification
9. [DBG18110167][WDS] multicast traffic can't pass throuth WDS link on 2.4g
10. [CWM] change power/channel issue when RF optimization.
11. [CWM] get channel DFS status according different country when RF optimization
12. [CWM] the register/boarding failure times issue.
13. [CWM] add message version/series name/module type/band type.
14. [CWM] a large number of ap upgrade issue at the same time.
15. [CWM] report issue when device ipv6 address changed.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc022

Hardware: 1A1G

Date: Oct 23, 2018

Problems Resolved:

1. [CP/Radius server] if user want to delete the second and the third Radius server , but it can't successfully.
2. [CP/IP Interface]Dynamic IP doesn't show completely(same as BTD2018010179)
3. [SCAN]Scan function doesn't work in 5G band
4. [DFS]KR disable DFS channel
5. [CWM]Adjust local dynamic ipv6 and syslog.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc021

Hardware: 1A1G

Date: Oct 12, 2018

Problems Resolved:

1. [System Name]The AP's MDNS name and system name only allows maximum 64 characters
2. [CP/radius server] if set the same IP address for three server, it should be pop a warning message.
3. [CP/Radius server] if user want to delete the second and the third Radius server , but it can't successfully.
4. [IP Filter]This function doesn't work normal sometimes.

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc020

Hardware: 1A1G

Date: Sep 28, 2018

Problems Resolved:

1. [Daylight Saving Offset]Some Time zone doesn't work normal
2. [Taffic Control] The WDS's interface needs adjust
3. [provide system settings] system time doesn't work normal

4. [Multi Priority]This function doesn't work normal in 5G band
5. [CP/Radius server] Set the first and the third radius sever ,but the second is null ,after save , the third server is blank.
6. [Email Notification]This function doesn't work
7. [Captival portal] enable IP Interface, it can't pop the login page .
8. [IGMP]This function doesn't work normal

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc018

Hardware: 1A1G

Date: Sep 20, 2018

Problems Resolved:

9. [Daylight Saving Offset]Some Time zone doesn't work normal
10. [Taffic Control] The WDS's interface needs adjust
11. [HQ20170927000001][d-lab]Invalid MAC Address can't be imported to MAC Address List, but the "access control status" will be take effect.
12. [VLAN port list]PVID doesn't show completely
13. [suggest]traffic control and VLAN need add descriptive text in WDS mode
14. [log server]Input some special character will cause web show error
15. [WDS SCAN]When apc change to wds the scan function doesn't work normal
16. [hidden page]Domain show error
17. [CWM] [Log / SNMP Traps]: CWM just can receive enterpriseSpecific type trap

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc017

Hardware: 1A1G

Date: Sep 10, 2018

Problems Resolved:

1. [Daylight Saving Offset]Some Time zone doesn't work normal
2. [CWM /Monitor]: AccessPoint list , the values of Channel are not match with DUT

3. [channel]5G channel doesn't work normal
4. [help]IP filter must remove to Filter page
5. [VLAN]WDS VLAN doesn't work
6. [CWM]: When set wireless as OFF, Monitor >> AccessPoint list and Dashboard >> Channel Utilization list still can list the channel value
7. [Taffic Control] The WDS's interface needs adjust
8. [VLAN]MG VLAN doesn't work normal
9. [CWM /Monitor]: Wirelss Client list, can't get client's IPv6 Address
10. [CWM /Monitor]: Client information not match with AP web
11. [CWM /Monitor]: Wireless Client list, Up time error
12. [CWM]: SSID, User Authentication\External Captive Portal:用戶認證不成功

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc016

Hardware: 1A1G

Date: Aug 23, 2018

Problems Resolved:

1. [provide system settings]This function doesn't work
2. [System name setting]The system name must not support blank
3. [WDS with AP]Multi1 must not changed by user
4. [CWM]SSID, The item of WMM can't take effect.
5. [Daylight Saving Offset]Some Time zone doesn't work normal
6. [CWM /Monitor]: Wirelss Client page, can't get the values of User Name and Host Name
7. [CWM /Monitor]: Wirelss Client page,the value of Client Radio Type show wrong
8. [Multi SSID]Multi SSID1 doesn't work
9. [WDS Auto Channel Selection]This function doesn't work normal
10. [mib]Some function need remove in mib
11. [Multicast rate]This function doesn't work normal in 2.4G Multi SSID
12. [DDP] after disable dv8_agent from WEB UI, the managed by NMS status error
13. [DDP] set ip to DHCP/static failed
14. [CWM] wlan id and bssid issue in client associate.
15. [CWM] airtime firness and band steering issue.
16. [CWM] daylight setting issue.

17. [CWM] new ipfilter handle.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc014

Hardware: 1A1G

Date: Aug 10, 2018

Problems Resolved:

1. [provide system settings]This function doesn't work
2. [WDS SCAN]WDS SCAN doesn't work
3. [band steering]The SSID of 2.4G and 5G can set diffence
4. [Administation Settings]The password of Admin must support 64 characters
5. [wds info]Root WDS info show error
6. [System name setting]The system name must not support blank
7. [wds auto channel]This function can't enble in wds mode
8. [WDS with AP]Multi1 must not changed by user
9. [WDS WEP]WDS WEP doesn't work normal
10. [IPv6]The alter message show error
11. [Email log Schedule]When log is full AP will send email log two times
12. [Administrator] The item of "Certral wifi manager setting" can set enable. It show disable and gray in the default setting.
13. [DHCP]This function doesn't work normal
14. [captive portal] Web Redirection Only:URL Path's max length only support 120 ,not 128.
15. [CWM]: SSID, The WPA-Personal and WPA-Enterprise can't take effect.
16. [CWM]: AP Device information, The information of Central Wifimanager will show wrong.
17. [CWM]: SSID, The item of WMM can't take effect.
18. [client information] the System Information show "unknown"all the time .
19. [CWM]: SSID, DEL Multi-SSID, upload configuration, the AP will reboot all the time.
20. [captive protal] username/password : if set 64 characters of password, it can set successfully,but it show 32 characters in web page
21. [captive portal] login page : Test in IOS of iphone, "Use Policy" can't click successully. so user can't connect with AP all the time
22. [ACL file upload]Upload wrong ACL file will cause web page show error
23. [Daylight Saving Offset]Some Time zone doesn't work normal

24. [channel list]Some country channel list show wrong
25. [mib]The mib name show 2682
26. [SNMP settings]This function can not save success
27. [CWM][Bandwidth Optimization]: "Allocate Maximum bandwidth for each station
28. [CWM]: SSID, The Multi-SSID'Auth type will show wrong in Wireless client.
29. [CWM /Monitor]: Wirelss Client page, can't get the values of OS,User Name and Host Name

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v2.00-rc012

Hardware: 1A1G

Date: July 18, 2018

Problems Resolved:

18. Remove Alpha WDS use QCA's WDS
19. Remove AP Array
20. Support CWM v2.00
21. Support DDPv5/APP
22. Band streeing use QCA Band steering
23. Remove bandwith Optimzation -> Allocate different BW for 11a/b/g/n stations
24. In default settings, the network ip address setting is Dymatic ip
25. Support MDNS (See D-Link AP and Router Device Management v1.05)
26. Modify Timezone settings(See Timezone Mapping update0516)
27. Update country selection table(See Country-domain Mapping table_0516)
28. Airtime Fairness support(QCA)
29. Support FCC DFS2
30. Add new country domain, HK
31. Default admin user name/password is admin/admin

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc011

Hardware: 1A1G

Date: April 4, 2018

Problems Resolved:

1. [AP][autorfc client] More result information of wireless scan will caused the autorfc process crashed, and there will be not wireless initialization process when autorfc enabled.
2. [AP][ap array] mutissid autorekey/enable xmldb node cannot be sync to slave and backup master. This will cause the hostapd cannot start successful.
3. [AP][ap array] fixed the issue taht backup master cannot sync config from master when the backup device translate role from master to backup master.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc010

Hardware: 1A1G

Date: March 8, 2018

Problems Resolved:

1. [DBG18020148] traffic-control_bandwidth limit not follow the radio mode.
and Modify the max rate.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50

Firmware: v1.00-rc009

Hardware: 1A1G

Date: March 7, 2018

Problems Resolved:

1. [DBG18020234] AP-Array_DAP-2680 will crash after AP array work with auto-RF.
2. [DBG18020215] When CWM server enable AUTO-RF and push config to DUT, DUT will continuous reboot until reset to default.
3. [DBG18020148] traffic-control_bandwidth limit not follow the radio mode (DKP1610019-0072).

4. [DBG18020070] CP_NAS-IP-Address show the loop-back IP within Radius Authentication.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc008

Hardware: 1A1G

Date: January 8, 2018

Problems Resolved:

- 1.[LAN]Set IPmode to dynamic the DNS show blank.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc007

Hardware: 1A1G

Date: January 4, 2018

Problems Resolved:

1. [AP Array Tool+ Auto RF] If set Group from ap array tool., then enale auto RF in WEB, the function of Auto RF will be works normally.
2. [EAP]EAP-WPA doesn't work normal when use DWA-171 or TL-WDN3321.
3. [Module]: Home->Site, the 2.4G will show off all the time.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc006

Hardware: 1A1G**Date: December 22, 2017****Problems Resolved:**

4. [telnet]This function doesn't work.
5. [Module] Home->Site->WLAN traffic statistics, the function of clear cannot take effect.
6. [LAN dynamic]When AP LAN Port set to DHCP client, AP did not immediately re-init DHCP.
7. [VLAN+ARP spoofing prevention]This function doesn't work normal.
8. [Module] DAP 2680 can't online on CWM Server that using Dynamic DNS.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0**Qcmbr:** 10.4-spf50cs1

Firmware: v1.00-rc005**Hardware: 1A1G****Date: December 7, 2017****Problems Resolved:**

1. [IxVeriwave] 2.4G and 5G maximum clients don't match with each other.
2. [Firmware protection, v1.00rc002] Firmware can be extracted by binwalk.
3. [Auto RF] In fw V1.00RC004, if set Auto RF enable in master AP, it can' Synchronization this parameter to other slaves.
4. [AP Array] some paramters can't synchronziation .
5. [security] 2680 firmware can using binwalk to extract files.
6. [Module] Configuration->SSID->CP->IP Filter settings, this function cannot take effect.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0**Qcmbr:** 10.4-spf50cs1

Firmware: v1.00-rc004**Hardware: 1A1G****Date: November 28, 2017****Problems Resolved:**

1. [zone defence]This function doesn't work in 5G band.
2. [LAN-DNS]Dynamic IP change to static IP will cause DNS disappear.

3. [Module]Monitor->Report->Rogue AP, click Detect, it will show 2.4G's rogue AP only sometimes.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc003

Hardware: 1A1G

Date: November 21, 2017

Problems Resolved:

1. [VLAN]VLAN doesn't work normal in WDS mode.
2. [AP array]{1Backup master+3Slave}+Master. The First time enable array and Input username & password in master AP,it can't enjoy the array group .
3. [performance]AP client mode has low rate of 2.4G and failed in 5G.
4. [Module] Configuration->Performance, the wireless mode and channel width in 5G.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc002

Hardware: 1A1G

Date: November 8, 2017

Problems Resolved:

1. [EU syslog] the function of EU syslog can't work normally.
2. [cli]Set IP by CLI will cause user can't access ap web.
3. [Multicast rate]Multicast rate doesn't work normal in 2.4G band.
4. [VLAN]Multi port VLAN doesn't work normal.
5. [channel list]Korea channel list is error.
6. [zone defence]This function doesn't work in 5G band.
7. [CP+Multi7]Some website doesn't need authentication.

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1

Firmware: v1.00-rc001

Hardware: 1A1G

Date: September 30, 2017

Problems Resolved:

First Release

Enhancements:

None

Known issues:

None

QCA Wireless Driver Version: qca-wifi-10.4-spf5.0

Qcmbr: 10.4-spf50cs1
