



**Firmware Version:** 1.02rc020  
**Published Date:** 2010/11/30

**Content:**

Upgrading Instructions:..... 2

    Upgrading by using Web-UI ..... 2

New Features:..... 2

Changes of MIB & D-View Module:..... 2

Problems Fixed: ..... 2

Known Issues: ..... 3

Related Documentation: ..... 3

## Revision History and System Requirement:


| Firmware Version | Date       | Model    | Hardware Version |
|------------------|------------|----------|------------------|
| 1.02rc020        | 2010/11/30 | DAP-2690 | A1               |

## Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

### Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.  
To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



## New Features:

None

## Changes of MIB & D-View Module:

None

## Problems Fixed:

| Firmware Version | Problems Fixed                                            |
|------------------|-----------------------------------------------------------|
| V1.02            | F/W : Closed a publicly disclosed potential vulnerability |

**Known Issues:**

---

| <b>Firmware Version</b> | <b>Known Issues</b> |
|-------------------------|---------------------|
| V1.02                   | None                |

**Related Documentation:**

---

- DAP-2690 User Manual v1.0