



Firmware Version: 3.16rc100
Published Date: 2016/03/29

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... 2

New Features:..... 3

Changes of MIB & D-View Module:..... 3

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
3.11rc078 3.15rc091	2015/01/20 2015/07/09	DAP-2690	B1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

The screenshot displays the D-Link DAP-2690 Web-UI interface. The top navigation bar includes links for Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with 'DAP-2690' expanded, containing 'Basic Settings', 'Advanced Settings', and 'Status'. The main content area is titled 'System Information' and lists the following details:

Model Name	DAP-2690
Firmware Version	3.16 14:01:23 03/21/2016
System Name	D-Link DAP-2690
Location	
System Time	03/29/2016 14:01:50
Up Time	0 Days, 00:4:8
Operation Mode(2.4GHz)	Access Point
Operation Mode(5GHz)	Access Point
MAC Address(2.4GHz)	9c:d6:43:29:04:90
MAC Address(5GHz)	9c:d6:43:29:04:98
IP Address	192.168.0.202

New Features:

None

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V3.16	1. Fixed security issue of web server is vulnerable to buffer overflow while parsing the cookie.

Known Issues:

Firmware Version	Known Issues
V3.16	None

Related Documentation:

- DAP-2690 User Manual v3.11