



Firmware Version: v2.00r131
Published Date: 2019/09/18

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... **Error! Bookmark not defined.**

New Features:..... 3

Changes of MIB & D-View Module:..... 3

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
v1.20rc075	2016/09/14	DAP-2695	Ax


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



The screenshot shows the D-Link DAP-2695 Web-UI interface. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows the navigation menu with DAP-2695, Basic Settings, Advanced Settings, and Status. The main content area displays the System Information page, which lists various system parameters:

System Information	
Model Name	DAP-2695
Firmware Version	v2.00 11:21:58 08/05/2019
System Name	D-Link DAP-2695
Location	
System Time	01/01/1970 08:01:41
Up Time	0 Days, 00:1:42
Operation Mode(2.4GHz)	Access Point
Operation Mode(5GHz)	Access Point
MAC Address(2.4GHz)	00:26:95:12:84:70
MAC Address(5GHz)	00:26:95:12:84:78
IP Address	192.168.0.106

New Features:

1. Use QCA's WDS
2. Remove AP Array
3. Support Nuclias Connect
4. Support DDPv5/APP
5. Use QCA's Band steering
6. In default settings, the network IP address setting is Dynamic IP
7. Support MDNS
8. Modify Time zone settings
9. Update country selection table
10. Move IP filter settings page from Captive Portal to Filter folder, behind WLAN Partition (AP GUI). IP filter function is independent feature and can work with all non-captive portal authentication.
11. Default admin user name/password is admin/admin
12. Add setup Wizard when first login

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V2.00	1. D-track -> Fix wrong RADIUS accounting attribute

Known Issues:

Firmware Version	Known Issues
V2.00	None

Related Documentation:

- DAP-2695 User Manual v2.00