

DCH-S160 Firmware Release Notes

Firmware: FW v1.01

Hardware: Rev.A1

Date: 2018/10/14

Problems Resolved:

1. Fixed Action button or change batteries takes 300sec into sleep mode.
2. Firmware upgrade low battery requirement change from 50% to 20%.
3. Fixed device binding failed through Huawei Router to access internet.
4. Fixed firmware upgrade issue when device under wake-up mode.

Enhancements:

1. Add blinking RED LED indicate device lots its Wi-Fi connection.
2. Add battery status change event whenever battery remaining power changing.
3. Add sensor status change event whenever water sensor status changing.

Known Issues:

None

----- END -----