



## DCH-S161 Firmware Release Notes

**Firmware: v1.05B07**

**Hardware: Rev.A1**

**Date: April 20, 2020**

### **Problems Resolved:**

1. Fixed the connection issue to some routers with smart connect feature enabled during the installation.
2. Fixed the issue of missing the notification when the water detection status is changed during the period of waking up process.
3. Added push notification for connection test by pressing the button during power saving mode.
4. Extended timeout after binding successfully to 10 minutes

### **Enhancements:**

None

### **Known Issues:**

None

---