



Firmware Version: V2.01
Prom Code Version: N/A
Published Date: 2018/10/29

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2015/06/16	DCS-4602EV	A1
V1.01	2015/06/30	DCS-4602EV	A1
V1.02	2015/10/05	DCS-4602EV	A1
V1.03	2015/10/12	DCS-4602EV	A1
V1.04	2016/2/2	DCS-4602EV	A1
V1.05	2017/1/6	DCS-4602EV	A1
V2.00	2018/5/4	DCS-4602EV	B1
V2.01	2018/10/29	DCS-4602EV	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in ".pkg" file format.
2. Log-in camera web UI and enter **Setup/Advanced Setup/System configuration/Firmware upgrade**
3. Click Browse... and specify the firmware file.
4. Click Upload. The camera starts to upgrade and will reboot automatically when the upgrade completes.

Notice: HW B1 is applied with different platform, the FW can't not be backward compatible with HW A1.

New Features:

Fireware Version	New Features
V2.00	New GUI (Ver. 3)

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.02	1. Fixed no live video issue when image setting at 4:3, 1280x960 / 1024x768 resolution. 2. Fixed flicking image when anti-flicker setting =50Hz 3. Remove the SD card information on Event Setup help hints page.
V1.02.02	1.Fixed the security issue of tunneling RTSP streaming over HTTP 2.Fixed the Cross-Site Scripting(XSS) issue 3.Fixed the Cross-Site Request Forgery (CSFR) issue

V1.03.00	1. Upgrade to new signing keys for fixing Code-Signing Key issue
V1.04	- Enhancement for security issue: - Support TLS 1.1/1.2. - CSRF protection default enable. - A warning message popped up for that Chrome V45 (or higher) cannot support plugin. - Fixed snapshot/video recording issue while browse UI in IE11. - Fixed flicker issue. - Fixed MG-SOFT cannot connect the camera via SNMPv1, SNMPv2c, or SNMPv3. - Fixed Curl issue -mail server SMTP authentication fail. - Fixed Day&Night mode not to trigger while switching in between two modes.
V1.05	- Support ONVIF V16.07 - Support SHA 256 - Upgrade OpenSSL to 1.0.1t - Fixed minor issues
V2.01	- Update digital sign - Bug fixed, D-Track [DRU20180711000004] – Incorrect Tab name display on “Image settings” of web UI. Tab “Image” changes to “Image and Audio” while switching to another setting items. - Bug fixed, D-Track [DRU20180907000001] –Incorrect input of the Network Storage Location address. - Bug fixed, stream issue with DNR-322L. - Bug fixed for D-Lab minor issues.

Known Issues:

Firmware Version	Known Issues
V2.00	Do not support H.265 decode on MAC.

Related Documentation:

N/A