



Firmware Version: V1.03

Published Date: 2021/09/24

Content:

Upgrading Instructions: 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2016/12/28	DCS-4703E	A1
V1.01	2017/9/26	DCS-4703E	A1
V1.02	2019/04/25	DCS-4703E	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file to your hard drive from the D-Link website.
2. Log-in camera web UI and go to **Maintenance/Firmware** web page upgrade
3. Locate the file (upgraded firmware) on your hard drive by clicking **Choose File**.
4. Click **Upload** to upgrade the firmware on your camera.

New Features:

Fireware Version	New Features
V1.00	1.New model MP FW release
V1.01	1. Support D-Link new XSS Specification 2.0.0. 2. Support D-Link new rule signing digital signature. 3. Support Japanese language.

Problems Fixed:

Firmware Version	Problems Fixed
V1.01	Enhancements: 1. Update html version to v2.02.08_min. 2. Update copyright information to 2017. 3. Modify ONVIF device information and scope name. Problem resolved: 1. Fixed issue of "When login or edit new password is not encrypted strongly" (D-Lab).
V1.02	Enhancements: 1. Update new digital sign 2. User name and password is required for FTP/NAS relative settings.

	Problem resolved: 1. Fixed issue of data in snapshot file name [D-Track DEUR2018012400004] 2. Fixed issue of "Network storage" server [D-Track DEUR20180910000003] 3. Fixed of issue of FTP/NAS can useable w/o ID/PWD. Fixed issue of "save, don't save" button for video setting.
V1.03	1. Remove DDNS server address www.dlinkddns.com 2. Fixed SSL/TLS vulnerability issue (Remove TLS V1.0 and V1.1). 3. Fixed CGI command to get the account password.(Sim issue Ref#013221) 4. Fixed Bug for "manual setting time can't set time after 2020". 5. Fixed D-Track Bug HQ20191122000006 for "Issues with MailProvider Freenet" This case cause on Customer's mail server not support special characters "-" and "_". 6. Fixed D-Track Bug HQ20200611000006 for " button "Copy your Computer's Time Settings" not working." 7. Fixed D-Track Bug HQ20200527000011 for "TimeSettings reset to default value after reboot." 8. This version will clear the log when restoring factory defaults

Known Issues:

Firmware Version	Known Issues
	N/A

Related Documentation:

N/A